




A Division of Thiessen Products, Inc.

INSTRUCTION SHEET FOR #94557-55A

COMPENSATING SPROCKET WRENCH - NEW 1/2" DRIVE

USE TO REMOVE AND INSTALL COMPENSATING NUT

USE ON BIG TWIN & SPORTSTER 1955-70

*WARNING: Disconnect negative battery cable to avoid accidental start-ups.*

1. Refer to H-D® Service Manual for removal of primary cover.
2. Install tool with the two dowel pins seated in compensating nut as far as possible, before removing or installing nut.

PARTS AVAILABLE SEPARATELY

No.	Qty.	Description	Part No.
1	2	PINS	2015

CAUTION: WEAR SAFETY GLASSES. EXCESSIVE FORCE MAY DAMAGE PARTS AND TOOL.
 SEE JIMS® CATALOG FOR OVER 100 OTHER TOP QUALITY PROFESSIONAL TOOLS.
 THE LAST TOOLS YOU WILL EVER NEED TO BUY.

555 DAWSON DRIVE, CAMARILLO, CA 93012 PHONE 805-482-6913 • FAX 805-482-7422




A Division of Thiessen Products, Inc.

INSTRUCTION SHEET FOR #94557-55A

COMPENSATING SPROCKET WRENCH - NEW 1/2" DRIVE

USE TO REMOVE AND INSTALL COMPENSATING NUT

USE ON BIG TWIN & SPORTSTER 1955-70

*WARNING: Disconnect negative battery cable to avoid accidental start-ups.*

1. Refer to H-D® Service Manual for removal of primary cover.
2. Install tool with the two dowel pins seated in compensating nut as far as possible, before removing or installing nut.

PARTS AVAILABLE SEPARATELY

No.	Qty.	Description	Part No.
1	2	PINS	2015

CAUTION: WEAR SAFETY GLASSES. EXCESSIVE FORCE MAY DAMAGE PARTS AND TOOL.
 SEE JIMS® CATALOG FOR OVER 100 OTHER TOP QUALITY PROFESSIONAL TOOLS.
 THE LAST TOOLS YOU WILL EVER NEED TO BUY.

555 DAWSON DRIVE, CAMARILLO, CA 93012 PHONE 805-482-6913 • FAX 805-482-7422